BOREWELL COMPLETION REPORT

08/01/2022

VINAYAKA ENTERPRISES

Mob : 7411900632 | 8553736422

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bengaluru 560 094

No. : 752

1. Customer's Name and Address : Assistant Executive Engineer

with Telephone No. Vidyaranyapura sub-division.
BBMP Bangalore

2. Well Location : Gurudarshan layout

3. Total Well Depth / Drilled in Ft. : 1315 ft

4. Casing Erected in Ft. : 10 PVC - 60ft 7MS - 270 ft

5. Water Struck st the Depth of : 980ft

6. Total Yield (Measuring Method "V" Norch : 2 1/2

7. Formation of Soil/Well Water Condition : ~~Boulders~~/Silt/Loose Soil/Clear : Coutur

8. At the Depth of : 980ft (Boulders)

9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is on way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Propristor

BOREWELL COMPLETION REPORT

08/01/2022

VINAYAKA ENTERPRISES

Mob : 7411900632 | 8553736422

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bengaluru 560 094

No. : 751

1. Customer's Name and Address : Assistant Executive Engineer
with Telephone No. Vidyaranyapura Sub division.
BBMP Bangalore. 97, Vidyaranyapura.

2. Well Location : Thindlu, vidyaranyapura.

3. Total Well Depth / Drilled in Ft. : 1350 ft

4. Casing Erected in Ft. : 14 PVC — 60 Pl — 9ms 270 Pl

5. Water Struck st the Depth of : 1020 ft

6. Total Yield (Measuring Method "V" Norch : 2½

7. Formation of Soil/Well Water Condition : ~~Boulders~~/Silt/Loose Soil/Clear : Boulders.

8. At the Depth of : 1020 ft

9. Recommended to use Jet Pump / Air Compressor / ~~Submersible~~ / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is on way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Propristor